

1. Basic Information

Contract/Job No:	MWC 1958s
Contract/Job Name	St Julians River BR-8 Span.
Grid Ref (e.g. SE 630 284):	ST321903
Location/Location Address:	Stockton Close, East Usk, St. Julians, Newport, Gwent, Wales, NP19 7HH, United
Site Manager's Name:	Mike Jones
Contact Tel. No:	07825681883
Maximum size of project team:	5
Client's Project Manager's Name and Contact email	Simon Mc Darren
Date you wish the work to commence: <i>Be realistic based upon the consent timescales given above!</i>	Works are on a 28-day remit risk score 12
Duration of the work (weeks):	2 shifts Max.
Daytime or Night time works;	Day/Night Working TBC.
Proposed hours of work:	8 Hours
Give a brief description of works to be carried out:	Missing bolt to rail bearer connection, replace missing bolt and explore potential to replace bolts that have become sheared at failed connection. investigate surrounding rail bearer connections for further signs of failure and replace bolted connections as appropriate. Location: 5th (from LM) Cross Girder/ Rail Bearer Connection Within Span 5.
Purpose of the works: (e.g. to support the structure)	As above
Equipment to expected be used:	Rope access equipment
Temporary works expected to be used:	N/A

Materials / products expected to be used:	Rope access equipment bolts lights TCB wrench
Will a site compound be set up?	NO
Will De-veg be required?	NO

Section 2 – Location Maps



Section 3 – Work Methods

Rope access to carry out the installation of missing bolts and a surrounding survey to establish if any more are loose or sheared.