




PHOTO 1 - OVERALL VIEW OF BOTTOM STAIR CASE



PHOTO 2 - VIEW OF EXPOSED REBAR ON LEFT OF STAIRCASE




PHOTO 3 - VIEW OF EXPOSED REBAR ON RIGHT OF STAIRCASE



PHOTO 4 - TOP OF STAIRCASE



BURIED SERVICES INFORMATION

ALL BURIED, SURFACE AND OVERHEAD SERVICE INFORMATION CONTAINED WITHIN THIS DRAWING IS SHOWN INDICATIVELY. THE SERVICES SHOWN MAY NOT REPRESENT THE ENTIRETY OF ALL SERVICES THAT MAY BE ENCOUNTERED. ALL SOURCE INFORMATION SHOULD BE REFERRED TO PRIOR TO UNDERTAKING WORKS ON SITE. CROUCH WATERFALL ACCEPT NO RESPONSIBILITY FOR OMISSIONS OR ERRORS IN THE POSITIONING OF THE SERVICES PRESENT ON SITE. REFER TO ALL RELATED ENGINEERING DRAWINGS, FORMS AND SPECIFICATIONS FOR FURTHER INFORMATION. REFER TO THE RESIDUAL/DESIGNERS RISK ASSESSMENT FOR ACTIONS TO MINIMISE AND MITIGATE RISK ASSOCIATED WITH KNOWN AND UNKNOWN SERVICES ON SITE.

- EXISTING OR UNCHANGED ITEMS
- MODIFIED OR ITEMS TO BE MOVED
- REDUNDANT OR ITEMS TO BE REMOVED
- NEW, PROPOSED OR ADDITIONAL ITEMS

