



Annexe C Photolog AST Removal



Photograph C-1: Inspection of the AST



Photograph C-2: Entrance to AST



Photograph C-3: Inspection of the AST



Photograph C-4: Prior to removal



Photograph C-5: Preparing for demolition



Photograph C-6: Removal of secondary containment



Photograph C-7: Secondary containment removed



Photograph C-8: Removal of AST



Photograph C-9: Removal of AST



Photograph C-10: Removal of AST



Photograph C-11: Removal of AST



Photograph C-12: Site conditions during works



Photograph C-13: Removal of materials



Photograph C-14: Removal of materials



Photograph C-15: Removal of materials



Photograph C-16: Surface post removal



Photograph C-17: Removal of materials



Photograph C-18: Removal of materials



Photograph C-19: Removal of materials



Photograph C-20: Surface post removal