


Notes

1. Survey information provided by Egnid Consulting Ltd.
2. All levels in metres Above Ordnance Datum Newlyn.
3. Do not scale from this drawing.
4. Any anomalies on this drawing should be brought to the attention of Egnid Consulting Ltd.
5. Key.

- Topographical Survey Contours
- SW1 Surface Water Monitoring Point
 - SW2 Ground Water Monitoring Point
 - SW3 Leachate Monitoring Borehole
 - SW4 Perimeter Gas Monitoring Borehole
 - SW5 Combined Gas / Groundwater Borehole
 - SW6 Dewatering Point
 - SW7 Landfill Gas Extraction Wells
 - SW8 Knockout Pot
 - SW9 Isolation Valve
 - SW10 Gas Well (Buried)
 - SW11 Gas Well (Decommissioned)
 - SW12 Gas Pin Well
 - SW13 Leachate Recirculation
 - SW14 Leachate Slump
 - SW15 Manhole
 - SW16 Manhole (Buried)
 - SW17 600mm Ø Pipe
 - SW18 450mm Ø Pipe
 - SW19 400mm Ø Pipe
 - SW20 350mm Ø Pipe
 - SW21 300mm Ø Pipe
 - SW22 250mm Ø Pipe
 - SW23 225mm Ø Pipe
 - SW24 180mm Ø Pipe
 - SW25 125mm Ø Pipe
 - SW26 110mm Ø Pipe
 - SW27 90mm Ø Pipe
 - SW28 60mm Ø Pipe
 - SW29 32mm Ø Pipe
 - SW30 Buried Pipework
 - SW31 Horizontal Pipework
 - SW32 Vertical Pipework
 - SW33 Condensate Lines
 - SW34 Air Lines
 - SW35 Sewer
 - SW36 Leachate Main Pipe
 - SW37 Gas Main
 - SW38 LF6 Trench

Rev	Modification	By	CHK	APP	Date
D	Location of cottage added	GR	IR	IR	17.10.24
C	Monitoring Man Amended	LE	IR	IR	23.07.24
B	General Amendments	GR	AC	AC	04.02.22
A	Monitoring Man Amended	JB	AC	AC	22.06.21



Egnid Consulting Limited
Unit 10, The Mill, Park Road, Bangor,
LL57 4PF, Gwynedd
Tel: 01824 565266
Email: info@egnid.com

Cyngor Sir Ynys Môn
Isle of Anglesey County Council

Penrhysgyn Landfill Site

Monitoring Locations

Drawn by	DMD	Checked by	GOUR	Approved by	IR
Date	07.01.2015	Date	07.01.2015	Date	07.01.2015
Status	Information			Scale @ A1	1:1900
Drawing Number	5379.SURV.D03				Revision
					D

