

Schedule 5 Notification


PART A

Permit Number:	BR9715B
Name of Operator:	Solutia UK Ltd
Location of Installation:	Corporation Road, Newport, Gwent, NP194XF
Location of the emission:	T66 'New' Storage
Time and date of the emission:	17/06/2024 at ~21:00

Substance(s) emitted	Media e.g. air /water	Best estimate of the quantity or the rate of emission	Time during which the emission took place
T66 (Heat Transfer Fluid)	Release to adjacent ground	~7.5 tonnes	Approximately 15 minutes leading up to 21:00

<p>Description of the failure or accident, and...</p> <p>Measures taken, or intended to be taken, to stop the emission:</p>	<p>At the time & date detailed above, a spillage of T66 was observed externally to the 'New' storage bund. Initial indications are that a 'mag-drive' pump seal had failed, resulting in a loss to the small pump bund, and then to adjacent chippings area whilst a drumming operation was taking place</p> <p>The spillage was largely contained using spill kit inventory, with the intention to excavate & remove any contaminated ground for appropriate disposal - as informed by sampling & analysis. There was no discharge to the site effluent system</p> <p>Further information to follow in Part B</p>
---	--

* Signed:



Date: 18/06/2024

* authorised to sign on behalf of Solutia UK Ltd