

Schedule 5 Notification

PART A

Permit Number:	BR9715B
Name of Operator:	Solutia UK Ltd
Location of Installation:	Corporation Road, Newport, Gwent, NP194XF
Location of the emission:	Site Effluent Pipeline
Time and date of the emission:	16/11/23 – 8:30pm

Substance(s) emitted	Media e.g. air /water	Best estimate of the quantity or the rate of emission	Time during which the emission took place
Treated Effluent	Discharge to field, potentially into surface water	Pipeline leak Unquantified pending excavation	Before 8:30pm

Description of the failure or accident, and... Measures taken, or intended to be taken, to stop the emission:	At around 8:30pm the site was informed of a potential leak from the sites effluent pipe in a field in Traston Meadows (offsite). The site emergency response was initiated. The site was not discharging effluent at this time, effluent discharge had stopped at 7:50pm. The emission point was inspected and liquid at the suspected leak point sampled. The sample was confirmed to be Eastman effluent. Extensive sampling of the local area including watercourses has been undertaken. A plan for repair and additional inspection of this area of pipeline has been formulated and will be undertaken over the coming fortnight. The site processes will remain shut down until the repair is completed and the effluent system is running normally again. Detailed information on the; extent & nature of the integrity failure to follow in the Part B follow-up, along with a plan for any remediation that is required.
--	--

* Signed:



Date: 20th November 2023

* authorised to sign on behalf of Solutia UK Ltd