

MERTHYR (SOUTH WALES) LTD

WATER SPOT CHECK SAMPLING

Site Name:	Ffos-y-fran Land Reclamation Scheme				
Permit No:	EPR/DB3131AF/V005	Month:	March 2024	Date of inspection 25.03.24	

Reporting of emissions to water (other than to sewer)

Monitoring Point	Suspended Solids Consent limits	pH Consent limits	Date of Sample	Discharge Status	pH result	Sus Solids result	Iron as Fe (mg/l)	Weather Conditions
M1 (WC1 Final Effluent)	50 mg/l	5-9	25-03-24	Discharging	8.20	9	0.01	Showers
M2 (WC1 Storm)	N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M5 (WI Final Effluent)	50 mg/l	5-9	25-03-24	Discharging	8.40	<5	0.01	Showers
M6 (WI Storm)	N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M7 (WB Final Effluent)	50 mg/l	5-9	N/A	Not Discharging	N/A	N/A	N/A	
M8 (WB Storm)	N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M9 (WC Final Effluent)	50 mg/l	5-9	N/A	Not Discharging	N/A	N/A	N/A	
M10 (WC Storm)	N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M11 (WG Final Effluent)	50 mg/l	5-9	N/A	Not Discharging	N/A	N/A	N/A	
M12 (WG Storm)	N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M13 (WF Final Effluent)	50 mg/l	5-9	N/A	Not Discharging	N/A	N/A	N/A	
M14 (WF Storm)	N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M3 (WA Final Effluent)	50 mg/l	5-9	N/A	N/A	N/A	N/A	N/A	
M4 (WA Storm)	N/A	N/A	N/A	N/A	N/A	N/A	N/A	

**Notes: WA has not been constructed.
WB generally not discharging since pumping operations ceased.**

Name	██████████	Position:	Restoration Manager	Date:	08/05/2024
-------------	------------	------------------	---------------------	--------------	------------