

## Surface water environmental monitoring report

Your Ref: DP3733BK

18<sup>th</sup> July 2024

PPC Team  
Natural Resources Wales  
Rivers House  
Fortrain Road  
St Mellons Business Park  
Cardiff  
CF3 0EY

Attn: Luke Burton

Re: DP3733BK – Docksway disposal site. Latest Area 2 surface water monitoring results, round 244.

This report contains the results of surface water monitoring undertaken at Docksway disposal site in June 2024. Included in this report are summary tables showing the sample location details (table 1) and the field test results of each sample location, (table 2).

**Table 1 – Details of the sampling locations sampled during Round 244**

Sample reference	Sample locations
SW24	Oxbow Lake
C3_Asb	Cell 3 Settling lagoon

### Surface water quality assessment

**Table 2 – Summary of the testing results during Round 244**

Monitoring locations	Field temperature (°C)	Lab pH	Ammoniacal nitrogen (mg/l)	Field dissolved oxygen (%)	Biological oxygen demand (mg/l)	Suspended solids (mg/l)	Chemical oxygen demand (mg/l)
SW24	22.2 °C	8.1	<0.2	94.4	2.92	n/a	30.2
C3_Asb	22.9 °C	8.2	1.16	91.2	2.95	3.2	48.4

The surface water quality at location C3\_Asb (Round 244) was within the permit limits during this round for the parameters tested. There was no presence of an oily sheen on the surface of the water and the laboratory did not detect any asbestos fibres within the water sample.

The discharge points SW25 & SW26 were both dry during this sampling round.

### Conclusion

Newport City Council (NCC) will continue to monitor the surface water quality of Docksway disposal site in accordance with the aftercare monitoring plan for Area 1, the Environmental Permit (Table S3.2 of the Permit), and in accordance with the relevant discharge consent limits.

If you have any questions regarding this report, then please do not hesitate to contact us.

Yours sincerely,

[Redacted Signature]

- CC: [Redacted] NCC (Landfill Manager)  
[Redacted] NCC (Monitoring Technician)