

MERTHYR (SOUTH WALES) LTD				Form CP63-3 revB WATER SPOT CHECK SAMPLING					
Site Name:		Ffos-y-fran Land Reclamation Scheme							
Permit No:		EPR/DB3131AF/V005		Month:		September 2024		Date of inspection 27.09.24	
		Reporting of emissions to water (other than to sewer)							
Monitoring Point		Suspended Solids Consent limits	pH Consent limits	Date of Sample	Discharge Status	pH result	Sus Solids result	Iron as Fe (mg/l)	Weather Conditions
M1 (WC1 Final Effluent)		50 mg/l	5-9	27-09-24	Discharging	8.22	<5	N/A	Showers
M2 (WC1 Storm)		N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M5 (WI Final Effluent)		50 mg/l	5-9	27-09-24	Discharging	8.28	<20	N/A	Showers
M6 (WI Storm)		N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M7 (WB Final Effluent)		50 mg/l	5-9	N/A	Not Discharging	N/A	N/A	N/A	
M8 (WB Storm)		N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M9 (WC Final Effluent)		50 mg/l	5-9	N/A	Not Discharging	N/A	N/A	N/A	
M10 (WC Storm)		N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M11 (WG Final Effluent)		50 mg/l	5-9	N/A	Not Discharging	N/A	N/A	N/A	
M12 (WG Storm)		N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M13 (WF Final Effluent)		50 mg/l	5-9	N/A	Not Discharging	N/A	N/A	N/A	
M14 (WF Storm)		N/A	N/A	N/A	Not Discharging	N/A	N/A	N/A	
M3 (WA Final Effluent)		50 mg/l	5-9	N/A	N/A	N/A	N/A	N/A	
M4 (WA Storm)		N/A	N/A	N/A	N/A	N/A	N/A	N/A	
		Notes: WA has not been constructed. WB not discharging since pumping operations ceased. Review of Discharge Consents required in light of proposed alternative Restoration Scheme.							
Name				Position:	Restoration Manager		Date:	24/02/2025	