

IMAGES OF DAMAGE TO THE TOE AND APRON OF THE EXISTING ROCK REVETMENT



IMAGES OF DAMAGE TO THE EXISTING OUTFALL - WING WALLS, APRON & GRATING



 Llywodraeth Cymru Welsh Government  SHORELINE MANAGEMENT Wales CEDM Ltd Shoreline Management Wales Nantlleweth Cymmer PORT TALBOT SA15 3ND Mr Peter Kaminaris, Senior Property Surveyor, Economy, Treasury and Constitution Group Business and Regions, Property Infrastructure.. Mr Peter Kaminaris Senior Property Surveyor Email: howard@shorelinemanagement.co.uk Mobile: 07860 486 761		SA1 SOUTHERN REVETMENT REPAIR	
		LOCATION(s) SA1 - SWANSEA WATERFRONT	
DECEMBER 2025		IMAGES OF DAMAGE FOR REPAIR	