







Date	31/12/2025
Survey Instrument	Jerome H2S Analyser
Serial No.	60500142
Weather Conditions	NE - 2.0 mph, 0.4C 1007.6 Cold, Calm, Clear.
Technician	Lee Foulkes

Date	Jerome Clock	Adjusted Time	Location	Comment	Olfactory	Hydrogen Sulphide Analyser (ppb)	Hydrogen Sulphide Analyser (ppb)	Picture Record
31.12.25	06:47	N/A - Jerome Clock Correct	Richmond Tce	LF arrived abernant 06:45. Parked on hill near Richmond Tce.	No Odour	0.000	0.000	
31.12.25	06:51	N/A - Jerome Clock Correct	Abernant School		No Odour	0.000	0.000	
31.12.25	06:54	N/A - Jerome Clock Correct	Windsor Tce		No Odour	0.000	0.000	
31.12.25	06:59	N/A - Jerome Clock Correct	Greenways		No Odour	0.000	0.000	
31.12.25	07:02	N/A - Jerome Clock Correct	Pant-yr-Eos		No Odour	0.000	0.000	
31.12.25	07:06	N/A - Jerome Clock Correct	Werfa Close		No Odour	0.000	0.000	
31.12.25	07:09	N/A - Jerome Clock Correct	Werfa Lane		No Odour	0.000	0.000	
31.12.25	07:12	N/A - Jerome Clock Correct	Ros Wenalt		No Odour	0.000	0.000	
31.12.25	07:15	N/A - Jerome Clock Correct	Railway Bridge		Slight musky odour. Horses. Not specifically landfill type odour.	0.000	0.000	

31.12.25	07:23	N/A - Jerome Clock Correct	Leachate Line Crossing Point		No Odour	0.000	0.000	
31.12.25	07:29	N/A - Jerome Clock Correct	Railway Gate / Top Little Row		No Odour	0.000	0.000	
31.12.25	07:33	N/A - Jerome Clock Correct	Little Row		No Odour	0.000	0.000	
31.12.25	07:37	N/A - Jerome Clock Correct	Richmond Garden		No Odour	3.670	3.470	
31.12.25	07:44	N/A - Jerome Clock Correct	Richmond / Little Row Sign		No Odour	0.000	0.000	
31.12.25	07:48	N/A - Jerome Clock Correct	Back of Richmond		Slight musky odour. Damp.	0.000	0.000	
31.12.25		N/A - Jerome Clock Correct	Entrance to Moss Row from Abernant Road		No Odour	0.000	0.000	