






Back of Outfall



Front of Outfall



Existing Railing



Slipway



Reproduced from the Ordnance
Survey Mapping with the permission of
the Controller of H.M.S.O. Crown
Copyright, Conwy County Borough
Council, 100023380, 2018

KEY/NOTES

First angle
Projection



1. Any anomalies on this drawing should be brought to the attention of Conwy County Borough Council.

REV	DETAIL	DRAWN	CHECKED	DATE

PROJECT

PENMAENMAWR OUTFALL REPAIR WORKS

TITLE

EXISTING PHOTOS

CLIENT

F R & I

SCALE @ A4:	DRAWN: DD	CHECKED: GP	APPROVED: BS	DWG STATUS:
N.T.S	DATE: 10.10.2018	DATE: 10.10.2018	DATE: 10.10.2018	ISSUE



ENVIRONMENT, ROADS & FACILITIES

G.B. Edwards BEng (Hons) CEng FICE
Head of Environment Roads & Facilities,
Mochdre Offices, Conway Road,
Mochdre, LL28 5AB.

Tel. (01492) 575337
Fax. (01492) 575199

PROJECT Ref:	DRAWING No:	REV
RM02 003 /	002	-