

Recycling Site Photos

EV Recycling Ltd.

Please note the following information when viewing the images below;

- The site has been recently acquired and is currently undergoing cleaning and maintenance activities.
- The images displayed are prior to the start of these activities.
- The logo shown on the building exterior is from the previous owner. This will be replaced with the EV Recycling logo.

Front of building and truck / emergency access gate at the side.





Impermeable surface area forecourt, flexible quarantine area & main shutter entrance



Hazardous storage area and indoor flexible quarantine area



recycling