Biffa Cardiff WMRC – Report into Activities 2019

A) Review of Monitoring

Emission monitoring of pH at point source (S1) discharge to sewer – see attached form.

B) Management System ISO14001 Action Plan

To ensure our responsibilities in relation to using appropriate third party disposal facilities are met
Target: Ensure all third-party disposal sites used by Biffa Hazardous Waste Division have undergone an appropriate audit within the last two years.

Action methods: Compile a master list of third-party sites currently in use. Review the audit history of these sites. Formulate an audit template. Develop an audit schedule that includes named individuals and expected completion dates for those sites without the appropriate information.

Progress – 25% of audits completed

C) Production/ Treatment data

Hazardous waste inputs 2019 – 1565.77 Tonnes
Hazardous waste treated 2019 – 0 Tonnes
Non Hazardous waste inputs 2019 – 962.63 Tonnes

D) Performance Parameters S5.3

Downtime of pH Probe – 0 days inoperative. See attached form

E) Details of any contamination or decontamination of the site which has occurred.

None