

Sewer Location Survey Feedback Form

SAP Order Number:	94928330	
Developer Services Ref (If available)		
Sewer(s) surveyed (with m/h refs where applicable):		
Size of sewer(s):	100mm	
Depth of sewer(s):	1.0m at point of interest to customer	
Sewer(s) material:	UPVC	
Other comments	<p>Pipework in good condition, served by SPS. SPS was located in wrong area, corrected. Area at which customer requires connection is on lateral line.</p>	

Check Item	Y	N
Location/Position of Public Sewer(s) confirmed:	Y	
Plan showing sewer location survey results attached (if different to public sewer record) – (dimensions from fixed points to accurately locate sewer)	Y	
Update sent to GIS Bureau?	Y	
Is there any evidence of surcharging within the system?		N
Is the pipe in good condition?	Y	
Any change in pipe diameter?		N
Any significant change of direction or gradient?		N
Any change in material?		N
Any significant sumps / backfalls?		N

NOF 003



Survey Completed by:	Andrew Gowman
Date:	02/04/19

For further information please contact:

Developer Services
Dŵr Cymru Welsh Water
Linea Building
Fortran Road
St Mellons
CF3 0LT
0800 917 2652

e-mail: ndcsewertrace@dwrcymru.com