

Schedule 5 -Notification Form

To be completed in the event of breach of Permit as required by Condition 4.3.1.

1. Complete section (a), (b) or (c) as relevant;
2. Sign and date the form
3. Scan and email or fax the form using the contact details below
4. Put signed copy in post and give copy to Environment Coordinator

Part A

Permit Number	EPR/ BL3986ID
Name of operator	Lafarge Tarmac Cement & Lime Limited
Location of Regulated Facility	Aberthaw Works, East Aberthaw, Barry, CF62 3ZR
Time and date of the detection	25.09.2019

(a) Notification for any malfunction, breakdown or failure of equipment, accident, or fugitive emission that could or is causing significant pollution

To be notified within 24 hours of detection

Date and time of the event	17-18.09.2019
Reference or description of the location of the event	Fugitive dust ; attributed to cooler tube crack
Description of where any release into the environment took place	Fugitive dust ; attributed to cooler tube crack
Substances(s) potentially released	Clinker
Best estimate of the quantity or rate of release of substances	Difficult to estimate but believed to be less than 1 tonne.
Measures taken, or intended to be taken, to stop any emission	Kiln due to be stopped on 19.09.2019 for temporary repair to be made, followed by replacement of cooler tube bend # 1 on Friday 27.09.2019
Description of the failure or accident.	Crack on cooler tube bend # 1

(b) Notification requirements for the breach of a limit

To be notified within 24 hours of detection unless otherwise specified below

Emission point reference/ source	Fugitive dust ; attributed to cooler tube crack
Parameter(s)	Dust
Limit	N/A
Measured value and uncertainty	N/A
Date and time of monitoring	N/A
Measures taken, or intended to be taken, to stop the emission	Kiln due to be stopped on 19.09.2019 for temporary repair to be made, followed by replacement of cooler tube bend # 1 on Friday 27.09.2019

Time periods for notification following detection of a breach of a limit	
Parameter	Notification period
N/A	N/A

(c) Notification requirements for the detection of any significant adverse environmental effect	
To be notified within 24 hours of detection	
Description of where the effect on the environment was detected	No Significant Environmental Impact detected
Substances(s) detected	No Significant Environmental Impact detected
Concentrations of substances detected	No Significant Environmental Impact detected
Date of monitoring/sampling	No Significant Environmental Impact detected

Part B – to be submitted as soon as practicable

Any more accurate information on the matters for notification under Part A	Crack identified in the cooler tubes
Measures taken, or intended to be taken, to prevent a recurrence of the incident	Kiln stopped to repair the cooler tube
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment which has been or may be caused by the emission	N/A
The dates of any unauthorised emissions from the regulated facility in the preceding 24 months	04.11.2019, 18.10.2019, 16.10.2019, 17-18.09.2019, 29.08.2019, 24.08.2019, 21.08.2019, 17.07.19, 09.07.2019, 02.07.2019, 21.05.2019, 05.05.2019, 11.04.2019, 10.04.2019, 05.04.2019, 02.04.2019, 01.04.2019, 29.03.2019, 21.03.2019, 20.03.2019, 16.03.2019, 13.03.2019, 06.03.2019, 05.03.2019, 04.03.2019, 24.01.2019, 28.10.2018, 23.10.2018, 22.10.2018, 08.09.2018, 07.09.2018, 13.08.2018, 11-12.08.2018, 18.07.2018, 22.03.2018, 11.12.02017, 23.10.2017, 09.10.2017, 01.10.2017, 27.07.2017.

Name	Kara Bennett
K.Bennett	K.Bennett
Date	25.09.2019
Post	Environmental Coordinator
Signatory authorised to sign on behalf of Lafarge Tarmac Cement and Lime Ltd.	

Incident notification: 0800 807060 (Freephone, 24 hour service)

Send completed form to:

Natural Resources Wales
Rivers House
St. Mellons Business Park
Cardiff
CF30EY

Fax Number: 029 20362095

Email: elizabeth.parr@naturalresourceswales.gov.uk
david.griffiths@naturalresourceswales.gov.uk