

Llanddulas photos from site visit 03.12.2020

Photo 1 – D287 surrounded by water



Photo 2 – D318 kinked pipework



Photo 3 – litter on southern flank of Cell 3A



Photo 4 – litter on southern flank of Cell 3A

