

Permit Number: EPR/BV9683IH

Operator: Dunbia (Wales)

Facility: Teify Park Abattoir and Meat Processing Plant

Form Number: Performance1 – 19/01/2021

Reporting of other performance indicators for the period 01/01/2020 to 31/12/2020

Parameter	Performance Indicator	Units
BOD	1.96	mg/l
Effluent discharge to sewer	0	m ³
Effluent discharge to River Teify	84,335	m ³
Waste disposal and/or recovery	10,083.9	t/yr
Imported Effluent	0	m ³

Operator's comments:

BOD recorded is average BOD for 2020.

Effluent discharge decreased in volume. This was in line with the decrease in water use.

Waste recovery and disposal was as follows; 7,320 tonnes of non-hazardous recovery and 2,763.583 tonnes of hazardous recovery. The decrease in non-hazardous waste in 2020 compared to 2019 was due to less cardboard and general waste as less meat was imported from New Zealand.

All waste was diverted from landfill in 2020.

No effluent was imported from Nantmel to Llanybydder in 2020.

Signed
(Authorised to sign as representative of Operator)

Date..... 29/01/2021