

Incident Summary Report

Incident :2104999 Location : Cwmtillery

Notification Details

Event Id	2104999	Logged by	Daniel Griffiths
Notified d/t	09/06/2021 13:28		
Reporter	Miss Lianne Turner	Organisation	Dwr Cymru / Welsh water
Tel No	07342 083127	Tel No	
F/B Reqd ?	No		
Incident Type	Water Pollution	Susp Source	Water Industry

DCWW SELF REPORTING - WATPOL

DATE/TIME OF UPDATE - 09/06/2021 13:19

REPORTED BY - Lianne Turner

CONTACT No. - 07342 083127

SAP REF - 315861334

ADDRESS / LOCATION OF INCIDENT Inc. ADDRESS / NGR / POSTCODE / ASSET No - Cwmtillery WTW, NP23 1LR. SO220060.

BRIEF DESCRIPTION OF INCIDENT - An operational incident has meant the water treatment works onsite clear water tank compartment 2 will need to be drained down. The water from the draindown enters the spillway of Cwmtillery reservoir.

DATE & TIME INCIDENT OCCURRED - 09/06/2021 12:45

DATE & TIME NRW INFORMED - 09/06/2021 13:00

WATERCOURSE AFFECTED - If No Please provide further Information - Spillway of Cwmtillery reservoir

DETAILS OF ACTION TAKEN/PLANNED [with date/time of completion] – An operational incident has meant the water treatment works onsite clear water tank compartment 2 will need to be drained down. The water from the draindown enters the spillway of Cwmtillery reservoir. Dechlorination will take place and manual samples taken for chlorine. NRW has been notified contact is John Goldsworthy

Incident Summary Report

Incident :2104999 Location : Cwmtillery

Location Details

Location:	Cwmtillery	Grid Reference:	SO2208306970
Catchment:	Ebbw Sirhowy C056003	Unitary Authority:	Blaenau Gwent - Blaenau Gwent
Area:	South East		

Assessment Details

Assessment Date Time:	09/06/2021 13:39	Incident Lead Officer:	Falk, Tamarind
Date / Time Attended:		Attended By:	
Attendance Justification:	Operator taken all appropriate action	Incident Confirmed As:	Event
Duplicate of:			

Incident Details

Incident Type:			
Principal Impact:		Principal Category:	
Secondary Impact:		Secondary Category	
Premises 1	Water Industry	Premises 2	Water Treatment Works
Pollutant 1		Pollutant 2	
Cause 1		Cause 2	
CausedByNRW:	No	Fish Kill:	No
Offence Occurred?:	No	Offender Known?:	
Polluter Identified:	No	Costs Recoverable:	No

Detail Notes:

Tamarind Falk

02/07/2021 17:02

Incident Summary Report

Incident :2104999 Location : Cwmtillery

Activity Date Time	Added By	Note
11/06/2021 08:00	Tamarind Falk	11/7/21 (08.00) DCWW Final received: Final Update- Discharge of clear water tank compartment 2 commenced at approx 15.45 on 9.6.21. Sodium thiosulphate was submerged into the washout chamber and the washout valve was opened and dechlorinated via the discharge pipework into the Spillway. Manual samples were taken for chlorine at approx. hourly intervals. Manual readings were on average 0.01mg/l with the highest reading of 0.07mg/l. Drain down of tank ceased at 21.45 on 9.6.21 and clear water tank compartment 2 was closed up to prevent any further discharge.
02/07/2021 16:41	Tamarind Falk	Chlorine below EQS = Event.

Incident Summary Report

Incident :2104999 Location : Cwmtillery

