



**NEATH PORT TALBOT
(RECYCLING) LTD**

Material Recovery & Energy Centre
Crymlyn Burrows, SWANSEA, SA1 8PZ
TELEPHONE 01792 641901
FAX 01792 465188

Form Number: BJ5775 – Ash 1

Reporting of Ash Composition for the Period from June 1st 2021 to June 30th 2021 – No Bottom Ash was produced – **Nil Result**

Ash Composition TOC & LOI:				
	TOC (%)	Limit (%)	LOI (%)	Limit (%)
Bottom Ash (Line 1 – incinerators 1 & 2 combined)		3		5
Bottom Ash (Line 2 – incinerators 1 & 2 combined)		3		5

Ash Composition (Metals, Dioxins, etc)																					
	Sb %	Cd %	Tl %	Hg %	Pb %	Cr %	Cu %	Mn %	Ni %	As %	Co %	V %	Zn %	Dioxin I-TEQ ng/kg	DIOXIN			DIOXIN LIKE PCBs			
															WHO – TEQ ng/kg			WHO – TEQ ng/kg			
															Humans/ mammals	Birds	Fish	Humans/ mammals	Birds	Fish	
Bottom Ash – Line 1 (Incinerators 1 & 2 combined)																					
APC residues – Line 1 (Incinerators 1 & 2 combined)																					

Name: R.Cirillo

Signed:**R.Cirillo**

Date: July 2nd 2021

On behalf of Neath Port Talbot County Borough Council MREC