



Your Ref: EAWML30058 DP3733BK  
Our Ref: 332510236/3505/CBH/VKR/MG/AREA 1 AND 2 SW

12<sup>th</sup> August 2021

PPC Team  
Natural Resources Wales  
Rivers House  
Fortrain Road  
St Mellons Business Park  
Cardiff  
CF3 0EY

**Attn: Tyrone Ward**

Dear Tyrone,

**Re: EAWML30058 and DP3733BK – Docksway Disposal Site. Latest Area 1 and 2 Surface Water Monitoring Results, Round 209.**

We write to provide details of the results of surface water monitoring undertaken at Docksway Disposal Site in July 2021 (Round 209).

With this letter report we enclose summary tables giving field observations and selected field test results for each of the surface water positions. The analytical certificates for the laboratory testing carried out during this monitoring round are included with this report.

Surface water sampling was carried out at four locations during Round 209, see Table 1 below.

**Table 1** Details of Locations Sampled during Round 209

Position Monitored	Location
SW1A	River Ebbw Upstream
SW23	Discharge to Maes Glas Pill from Docks Drain Outfall (Disused Culvert)
SW24	Oxbow Lake Position 1
C3_Asb	Cell 3 settling lagoon

Note: SW02 and SW7 were not monitored during this round due to unsafe access and SW25 and SW26 were recorded to be dry

### Surface Water Quality Assessment

Table 2 below shows selected testing results for Round 209. There are no compliance limits set for surface water and therefore there is no commentary regarding the results.

**Table 2** Testing Results Summary for Round 209

Monitoring Location	Field Temperature (°C)	Lab pH	Ammoniacal Nitrogen (mg/l)	Field Dissolved Oxygen (%)	BOD (mg/l)	Suspended Solids (mg/l)	Chemical Oxygen Demand (mg/l)
SW1A	19.8	8.42	<0.2	103.9	<1	-	10.1
SW23	14.1	7.83	21.6	61.1	2.63	-	32.4
SW24	24.7	8.31	<0.2	73.6	2.58	-	40.7
C3_Asb	25.3	8.51	<0.2	95.6	1.95	<2	79.2

The field operative did not record the presence of a sheen during sampling at C3\_Asb but did record the presence of algae visible at the surface. The laboratory did not detect asbestos fibres in the sample from

Caversham Bridge House  
Waterman Place  
Reading  
Berkshire RG1 8DN

Telephone: +44 (0)118 950 0761  
email: Reading.UK@stantec.com

Registered Office:  
Stantec UK Ltd  
Buckingham Court  
Kingsmead Business Park  
Frederick Place, London Road  
High Wycombe HP11 1JU  
Registered in England No. 01188070

C3\_Asb. The surface water quality within C3\_Asb was also within the Permit limits during Round 209 for the parameters tested.

Concluding Remarks

Newport City Council (NCC) will continue to monitor the surface water quality on and around Docksway Disposal Site in accordance with the aftercare monitoring plan for Area 1, the Environmental Permit, and in accordance with the relevant discharge consent limits. Stantec will continue to provide commentary on water quality with reference to point source emission limits to water (Table S3.2 of the Permit), and discharge consent limits within subsequent reports (as appropriate).

If you have any questions regarding the investigations carried out or the data herein, then please do not hesitate to contact us.

Yours sincerely



**Kate Riley**  
**Senior Associate**

on behalf of Stantec UK Ltd

Encls: Laboratory Certificates

CC: Silvia Gonzalez-Lopez – Newport City Council  
Robert Hughes – NCC (Docksway Disposal Site)  
Luke Embrey - NCC