






Appendix 20.4: Video stills of man-made items observed within Holyhead Harbour during ROV and DDV surveys

Transect No.	Video File	Time	Object Description	Image
001	ROYHOL0320_ROV_001_06_08_20	00:01:32	Lobster Pot	
001	ROYHOL0320_ROV_001_06_08_20	00:01:43	Lobster Pot	
003	ROYHOL0320_ROV_003_06_08_20	00:00:49	Mooring rope (modern)	
003	ROYHOL0320_ROV_003_06_08_20	00:01:01	Fishing equipment?	



Transect No.	Video File	Time	Object Description	Image
003	ROYHOL0320_ROV_003_06_08_20	00:01:15	Seaweed covered object, possibly geological	
003	ROYHOL0320_ROV_003_06_08_20	00:01:22	Seaweed covered object, possibly geological	 
003	ROYHOL0320_ROV_003_06_08_20	00:01:31	Rope and mesh object (fishing equipment)	




Transect No.	Video File	Time	Object Description	Image
				
003	ROYHOL0320_ROV_003_06_08_20	00:02:04	Possible metal ring	
003	ROYHOL0320_ROV_003_06_08_20	00:05:53	Metal hook	
003	ROYHOL0320_ROV_003_06_08_20	00:06:21	Anchor chain	

Transect No.	Video File	Time	Object Description	Image
003	ROYHOL0320_ROV_003_06_08_20	00:06:25	Metal objects and chain	
003	ROYHOL0320_ROV_003_06_08_20	00:06:36	Anchor	 
004	ROYHOL0320_ROV_004_06_08_20	00:01:03	Rope or piping	



Transect No.	Video File	Time	Object Description	Image
004	ROYHOL0320_ROV_004_06_08_20	00:01:16	Plastic lid	
004	ROYHOL0320_ROV_004_06_08_20	00:01:17	China cup or shell?	
005	ROYHOL0320_ROV_005_06_08_20	00:07:03	Wood and metal object or scour marks	
006	ROYHOL0320_DDV_006_29_11_20_0879	00:02:50	Tire	



Transect No.	Video File	Time	Object Description	Image
				
006	ROYHOL0320_DDV_006_29_11_20_0879	00:02:58	Tire	 
006	Waterfront TRO6	00:02:15	Wood	
009	ROYHOL0320_DDV_009_29_11_20_0806	00:01:53	Rope (modern)	



Transect No.	Video File	Time	Object Description	Image
009	ROYHOL0320_DDV_009_29_11_20_0806	00:03:02	Curved object, possibly rope	
009	Waterfront TR09	00:10:55	Broken wooden oar?	
009	Waterfront TR09	00:11:53	Chain	
010	ROYHOL0320_DDV_010_29_11_20_0784	00:06:34	Metal object/wire?	

Transect No.	Video File	Time	Object Description	Image
010	ROYHOL0320_DDV_010_29_11_20_0784	00:07:48	Broken wooden oar (modern)	
011	ROYHOL0320_DDV_011_29_11_20_0767	00:06:14	Lobster pot/plastic basket	
011	ROYHOL0320_DDV_011_29_11_20_0767	00:08:14	Metal object?	
011	ROYHOL0320_DDV_011_29_11_20_0767	00:08:39	Possible metal pipe	

Transect No.	Video File	Time	Object Description	Image
014	ROYHOL0320_DDV_014_29_11_20_0728	00:03:41	Metal pipe or rope	
015	ROYHOL0320_DDV_015_A_29_11_20_0631	00:12:24	Possible wood	
015	ROYHOL0320_DDV_015_A_29_11_20_0631	00:13:11 – 00:13:17	Anchor chain	 
015	ROYHOL0320_DDV_015_A_29_11_20_0631	00:14:47	Unknown broken object	

Transect No.	Video File	Time	Object Description	Image
015	ROYHOL0320_DDV_015_A_29_11_20_0631	00:15:19 – 00:15:53	Excavator scour marks or wooden planks	
016	ROYHOL0320_DDV_016_B_29_11_20_0608	00:06:26	Rectangular object	
016	ROYHOL0320_DDV_016_B_29_11_20_0608	00:02:19	Unknown object (possible boulder)	
016	Waterfront TR16	00:07:30	Metal object?	

Transect No.	Video File	Time	Object Description	Image
016	Waterfront TR16	00:07:30	Metal object	
017	Waterfront TR17	00:02:16	Chain	
017	Waterfront TR17	00:02:16	Chain	
017	Waterfront TR17	00:02:28	Long metal object possibly pipe	

Transect No.	Video File	Time	Object Description	Image
017	Waterfront TR17	00:06:32	Two long metal objects possibly pipes	
018	ROYHOL0320_DDV_018_29_11_20_0687	00:02:20	Object lodge in sediment	
020	ROYHOL0320_DDV_020_29_11_20_0660	00:02:25	Metal clip	
022	ROYHOL0320_DDV_022_29_11_20_0667	00:03:29 – 00:03:35	Large anchor chain	

Transect No.	Video File	Time	Object Description	Image
				