

## History record

**Job no.** M017721  
**Description** Verify accuracy of well head meters.  
**Work done**  
 Checked all ok.

<b>Job type</b>	<b>Shift</b>	<b>Project no.</b>	<b>Priority</b> 3	<b>Safety job</b>	<b>Work request</b>
-----------------	--------------	--------------------	----------------------	-------------------	---------------------

**Instruction no.** W-P/HOUSES2  
**Instruction description** Verify accuracy of well head meters.  
**Cost centre**  
**Cost centre name** Costcentre 2

<b>Equipment no.</b> W-PUMP	<b>Equipment description</b> Pump houses				
<b>Group</b> N/A	<b>Area</b> Outside	<b>Type</b> N/A	<b>Code</b> N/A	<b>Eq. project</b> N/A	<b>Line</b> N/A

<b>Date reported</b> 17/10/2015	<b>Time reported</b> 10:15:38	<b>Reported by</b> Auto generated	<b>Date acknow'd</b> 17/10/2015	<b>Time acknow'd</b>	<b>Acknow'd by</b>
<b>Date actioned</b> 17/10/2015	<b>Time actioned</b>	<b>Actioned by</b>	<b>Date completed</b> 27/10/2015	<b>Time completed</b> 11:00	<b>Completed by</b> Matt Mathias

<b>Hours worked</b> 2	<b>Downtime hours</b> 0	<b>Labour cost</b> 40	
		<b>Spares cost</b> 0	
		<b>Other costs</b> 0	
<b>Planned date</b> 22/10/2015	<b>Estimate hours</b> 0	<b>Overall cost</b> 40	

Remove 100 lts of water by bucket to check accuracy of gauges at the well heads of Tynant and Tau pump houses

## History record

**Job no.** M018190  
**Description** Verify accuracy of well head meters.  
**Work done**  
 All work has been carried out.

<b>Job type</b>	<b>Shift</b>	<b>Project no.</b>	<b>Priority</b> 3	<b>Safety job</b>	<b>Work request</b>
-----------------	--------------	--------------------	----------------------	-------------------	---------------------

**Instruction no.** W-P/HOUSES2  
**Instruction description** Verify accuracy of well head meters.  
**Cost centre**  
**Cost centre name** Costcentre 2

<b>Equipment no.</b> W-PUMP	<b>Equipment description</b> Pump houses				
<b>Group</b> N/A	<b>Area</b> Outside	<b>Type</b> N/A	<b>Code</b> N/A	<b>Eq. project</b> N/A	<b>Line</b> N/A

<b>Date reported</b> 24/04/2016	<b>Time reported</b> 12:24:25	<b>Reported by</b> Auto generated	<b>Date acknow'd</b> 24/04/2016	<b>Time acknow'd</b>	<b>Acknow'd by</b> Auto generated
<b>Date actioned</b> 24/04/2016	<b>Time actioned</b>	<b>Actioned by</b> Auto generated	<b>Date completed</b> 20/06/2016	<b>Time completed</b> 10:35	<b>Completed by</b> Matt Mathias

<b>Hours worked</b> 0	<b>Downtime hours</b> 0	<b>Labour cost</b>	0
		<b>Spares cost</b>	0
		<b>Other costs</b>	0
<b>Planned date</b> 29/04/2016	<b>Estimate hours</b> 0	<b>Overall cost</b>	0

System backflush using hypochlorite

## History record

**Job no.** M018649  
**Description** Verify accuracy of well head meters.

**Work done**

All work carried out with ken both meters out 10-20% told stan and simon all ok.

<b>Job type</b>	<b>Shift</b>	<b>Project no.</b>	<b>Priority</b>	<b>Safety job</b>	<b>Work request</b>
			3		

**Instruction no.** W-P/HOUSES2  
**Instruction description** Verify accuracy of well head meters.

**Cost centre**  
**Cost centre name** Costcentre 2

**Equipment no.** W-PUMP  
**Equipment description** Pump houses

<b>Group</b>	<b>Area</b>	<b>Type</b>	<b>Code</b>	<b>Eq. project</b>	<b>Line</b>
N/A	Outside	N/A	N/A	N/A	N/A

<b>Date reported</b>	<b>Time reported</b>	<b>Reported by</b>	<b>Date acknow'd</b>	<b>Time acknow'd</b>	<b>Acknow'd by</b>
17/12/2016	3:43:22	Auto generated	17/12/2016		
<b>Date actioned</b>	<b>Time actioned</b>	<b>Actioned by</b>	<b>Date completed</b>	<b>Time completed</b>	<b>Completed by</b>
17/12/2016			18/01/2017	16:13	Matt Mathias

<b>Hours worked</b>	<b>Downtime hours</b>	<b>Labour cost</b>	40
2	0	<b>Spares cost</b>	0
		<b>Other costs</b>	0
<b>Planned date</b>	<b>Estimate hours</b>	<b>Overall cost</b>	40
16/01/2017	0		

Remove 100 lts of water by bucket to check accuracy of gauges at the well heads of Tynant and Tau pump houses.

## History record

**Job no.** M018892  
**Description** Verify accuracy of well head meters.  
**Work done**  
 Checked all ok worked out slightly shy of 100lts on tau pump house.

<b>Job type</b>	<b>Shift</b>	<b>Project no.</b>	<b>Priority</b> 3	<b>Safety job</b>	<b>Work request</b>
-----------------	--------------	--------------------	----------------------	-------------------	---------------------

**Instruction no.** W-P/HOUSES2  
**Instruction description** Verify accuracy of well head meters.  
**Cost centre**  
**Cost centre name** Costcentre 2

<b>Equipment no.</b> W-PUMP	<b>Equipment description</b> Pump houses
--------------------------------	---

  

<b>Group</b> N/A	<b>Area</b> Outside	<b>Type</b> N/A	<b>Code</b> N/A	<b>Eq. project</b> N/A	<b>Line</b> N/A
---------------------	------------------------	--------------------	--------------------	---------------------------	--------------------

<b>Date reported</b> 17/07/2017	<b>Time reported</b> 15:29:02	<b>Reported by</b> Auto generated	<b>Date acknow'd</b> 17/07/2017	<b>Time acknow'd</b>	<b>Acknow'd by</b>
<b>Date actioned</b> 17/07/2017	<b>Time actioned</b>	<b>Actioned by</b>	<b>Date completed</b> 08/03/2018	<b>Time completed</b> 10:00	<b>Completed by</b> Matt Mathias

<b>Hours worked</b> 1.75	<b>Downtime hours</b> 0	<b>Labour cost</b> 35	
		<b>Spares cost</b> 0	
		<b>Other costs</b> 0	
<b>Planned date</b> 08/08/2017	<b>Estimate hours</b> 0	<b>Overall cost</b> 35	

Remove 100 lts of water by bucket to check accuracy of gauges at the well heads of Tynant and Tau pump houses.

## History record

**Job no.** M019338  
**Description** Verify accuracy of well head meters.  
**Work done**  
 All work carried out reported figures to Simon all ok.

<b>Job type</b>	<b>Shift</b>	<b>Project no.</b>	<b>Priority</b> 3	<b>Safety job</b>	<b>Work request</b>
-----------------	--------------	--------------------	----------------------	-------------------	---------------------

**Instruction no.** W-P/HOUSES2  
**Instruction description** Verify accuracy of well head meters.  
**Cost centre**  
**Cost centre name** Costcentre 2

<b>Equipment no.</b>	<b>Equipment description</b>				
W-PUMP	Pump houses				

  

<b>Group</b>	<b>Area</b>	<b>Type</b>	<b>Code</b>	<b>Eq. project</b>	<b>Line</b>
N/A	Outside	N/A	N/A	N/A	N/A

<b>Date reported</b>	<b>Time reported</b>	<b>Reported by</b>	<b>Date acknow'd</b>	<b>Time acknow'd</b>	<b>Acknow'd by</b>
04/09/2018	09:52:30	Auto generated	04/09/2018		

  

<b>Date actioned</b>	<b>Time actioned</b>	<b>Actioned by</b>	<b>Date completed</b>	<b>Time completed</b>	<b>Completed by</b>
04/09/2018			21/02/2019	14:44	Matt Mathias

<b>Hours worked</b>	<b>Downtime hours</b>	<b>Labour cost</b>	40
2	0	<b>Spares cost</b>	0
		<b>Other costs</b>	0
<b>Planned date</b>	<b>Estimate hours</b>	<b>Overall cost</b>	40
05/10/2018	0		

Remove 100 lts of water by bucket to check accuracy of gauges at the well heads of Tynant and Tau pump houses.