

Part A	
Permit Number:	PP3430UL
Name of Operator:	SRCL Ltd
Location of Installation:	Bridgend
Location of the Emission:	Fugitive emission - small amount of flock escaped from sheeting of Walking floor trailer as it was removed from site.
Date of Emission:	17/06/2021

Substance(s) Emitted	Media	Best Estimate of the Quantity or Rate of the Emission	Time During Which the Emission Occurred
flock	Off-site waste transfer	<50 litres	17 June 2021

Measures taken, or intended to be taken, to stop the emission.	the release was associated with a small quantity of material from the sheeting where the vehicle is loaded from.
--	--

Part B	
Any more accurate information on the matters for notification under Part A.	Investigation has been completed and the incident occurred on changeover from the loading of the vehicle. A small quantity of material overflowed from the loading point and was stuck underneath the sheeting, which on transfer off site the small quantity of material was released.
Measures taken, or intended to be taken, to prevent a recurrence of the incident.	An extra check has been introduced to ensure that the waste is contained prior to removal from site, and this is being trained to site personnel. Mesh netting has been applied to the fence.
Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission.	A team from the depot were dispatched from the site to contain and collect residues. These were then brought back to the depot for disposal. A road sweeper was also hired and was operated in the area on Saturday (19 th June), where remain residues were collected and disposed.

Name:*	Marianna Hislop
Position:	Permit Compliance Manager
Signature:	
Date:	21 st June 2021

* authorised to sign on behalf of SRCL Limited