

Permit Reference Number: BV8024IW

Operator: Glanbia Cheese Limited

Installation: Llangefni Dairy

Form Number: R1

Reporting of Waste Disposal and Recovery for the year 2018

Waste Description	Disposal		Recovery	
	Route	Tonnes	Tonnes	
1) Hazardous Wastes				
Named haz. Waste	LNGE	0.2		
Other hazardous wastes	TUBES/TANKS	0.12	-	
Total hazardous waste	Oil drums	0.65	-	
2) Non-Hazardous Wastes				
Named non-haz. Waste	LAND FILL	108.21	-	
Other non-hazardous wastes	LANDFILL	14.143	-	
Total non-hazardous waste	LANDFILL	48.2	48.2	
TOTAL WASTE				

Year	Named Waste	Total Waste (Tonnes)
2005	26,927	26,927
2006	21,203	21,203
2007	18,716	18,716
2018		

Operator's comments :



Signed Date 15-1-19
(authorised to sign as representative of the Operator)