

Your ref: DP3733BK

Our ref: 14739/3505/CBH/VKR

22nd February 2017

PPC Team
Natural Resources Wales
Rivers House
Fortran Road
St. Mellons Business Park
Cardiff
CF3 0EY

Peter Brett Associates LLP
Caversham Bridge House
Waterman Place, Reading
Berkshire RG1 8DN
T: +44 (0)118 950 0761
F: +44 (0)118 959 7498
E: reading@peterbrett.com

Attn: Mr David Willey

Dear David

RE: DP3733BK - Docksway Disposal Site. Latest Area 2 Groundwater Quality Monitoring Report, Round 154.

Please find enclosed the results of the groundwater quality monitoring undertaken at Area 2 of Docksway Disposal Site. Groundwater monitoring is required quarterly at the site in order to comply with Conditions 3.6.1 and 3.6.2 of the site PPC Permit. This report includes discussion on results obtained from monitoring undertaken on 21st December 2016. We enclose with this letter report the laboratory analytical certificates for the testing undertaken.

Field Observations

Details of the field testing of the Area 2 groundwater samples during Round 154 are presented in Table 1.

Table 1 – Field Testing Results and Observations

Monitoring Point	Date Monitored	Depth to Groundwater/Leachate (m)	pH	Electrical Conductivity (µS/cm)	Temperature (°C)	Dissolved Oxygen (%)
GW06_39	21/12/2016	4.55	7.26	6931	11.45	13.70
GW07_40	21/12/2016	4.40	7.71	2254	11.39	14.10
GW12_30	21/12/2016	4.90	6.98	2542	10.91	64.60
GW09_31	21/12/2016	4.90	7.15	2603	10.93	8.60
GW03_09	21/12/2016	8.30	7.42	1705	11.29	44.00
GW09_32	21/12/2016	7.90	6.78	1370	11.76	6.30
GW12_33	21/12/2016	8.60	7.06	3230	11.56	2.40
GW06_34	21/12/2016	8.25	7.03	1530	11.18	1.80
GW09_35	21/12/2016	8.00	7.97	13570	11.86	0.70
GW06_36	21/12/2016	6.65	7.95	10810	12.88	9.90
GW06_37	21/12/2016	6.00	7.40	14280	11.79	8.40
GW06_13	21/12/2016	6.35	7.53	9399	11.17	9.00
GW12_38	21/12/2016	5.40	7.04	2641	10.68	10.70
GW06_14a	21/12/2016	6.70	7.45	6460	11.80	27.90
LF08_07**	21/12/2016	N/A	7.82	10870	10.44	80.70
C2B**	21/12/2016	N/A	7.58	19480	17.45	43.50

** sampled from side risers closest to these leachate wells – due to access issues at the leachate wells



Laboratory Testing Results

Compliance Levels

The Control and Compliance limits for Area 2 are reproduced in Tables 2 and 3.

Table 2 –PPC Permit Compliance Levels for Emissions to Groundwater (Hazardous Substances)

Monitoring Well	Benzene	Naphthalene	Xylene	EPH	Arsenic
	Compliance Limit	Compliance Limit	Compliance Limit	Compliance Limit	Compliance Limit
	ug/l	ug/l	ug/l	ug/l	ug/l
GW03_09	2	5	3	Not Required	35
GW06_13	2	5	3	Not Required	50
GW06_14a	2	5	3	Not Required	25
GW06_34	2	5	3	Not Required	65
GW06_36	2	5	3	Not Required	30
GW06_37	2	5	3	Not Required	60
GW06_39	2	5	3	Not Required	50
GW07_40	2	5	3	Not Required	35
GW09_31	13	5	3	Not Required	80
GW09_32	3	5	3	Not Required	30
GW09_35	2	5	3	Not Required	50

Table 3 –PPC Permit Compliance Levels for Emissions to Groundwater (Non-Hazardous Substances)

Monitoring Well	Nickel		Potassium		Ammoniacal Nitrogen	
	Control Level	Compliance Limit	Control Level	Compliance Limit	Control Level	Compliance Limit
	ug/l	ug/l	mg/l	mg/l	mg/l	mg/l
GW03_09	8	10	160	180	30	35
GW06_13	12	14	100	110	30	35
GW06_14a	12	14	160	180	53	60
GW06_34	12	14	310	350	30	35
GW06_36	8	10	100	110	20	23
GW06_37	8	10	100	110	30	35
GW06_39	26.4	30	100	110	20	23
GW07_40	8	10	39.6	45	20	23
GW09_31	8	10	100	110	50	50
GW09_32	8	10	160	180	50	50
GW09_35	8	10	100	110	30	35

Compliance Limits have not yet been set for three replacement monitoring wells (GW12_30, GW12_33 and GW12_38).



Hazardous Substances (formally List I substances)

None of the hazardous substances agreed as “priority contaminants” exceeded the well specific Compliance Limits at the wells sampled during Round 154.

Non-hazardous Substances

None of the non-hazardous substances agreed as “priority contaminants” exceeded the well specific Compliance Limits at the wells sampled during Round 154.

Leachate Measurements

Leachate levels were not monitored in Area 2 during Round 154, or since March 2016 due to the leachate wells being closed (connected to the gas system to deal with odour issues).

The volumes of leachate removed from Area 2 during October, November and December 2016 are presented in Table 4. The leachate was sampled during R154 from side risers closest to the monitoring locations at LF08_07 and C2B, and the laboratory analytical certificates are attached to this letter report.

Leachate Removed

The volume of leachate removed from Area 2 (both Cell 1 and Cell 2 combined) is summarised in Table 4 below:

Table 4 – Quarterly Leachate Data from Area 2

Monitoring Round	Leachate Removed (tonnes)
Round 152 October 2016	1206
Round 153 November 2016	1254
Round 154 December 2016	1105

Concluding Remarks

None of the hazardous or non-hazardous substances agreed as “priority contaminants” exceeded the well specific Compliance Limits at the wells sampled during Round 154.

We are unable to comment on leachate levels in Area 2 at the current time.

PBA will continue to monitor and comment on the groundwater quality within subsequent reports. If you have any questions regarding the data, then please do not hesitate to contact us.

Yours sincerely

Kate Riley

For and on behalf of

PETER BRETT ASSOCIATES LLP

Cc. Gwyn Jones – NCC (Docksway Disposal Site)

Enc. Laboratory Analytical Testing Result