


Permit Reference Number: BL3986
Installation: Aberthaw Works
Reporting of Continuously Monitored Emissions to Air from Emission Point A1 for Oxides of Nitrogen for:


Operator: Lafarge Tarmac Cement & Lime Ltd
Form Number: Air 7 / 31 August 2010
Dec-14



NOx		Date		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31		
Daily Average	Monthly Summary		Daily Average ELV																																	
	Monthly Maximum	628.83	Daily Average	621	621	624	622	625	622	624	625.7	623	619	622	629	621	623	612	614	600	624	627	620			529	624	626	626	614	627.902	624.182	619.509	612.234		
	No. of invalid days	0	Value Valid? (if more than 5 dropped then N else Y)	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y			
	Total invalid 1/2 hours	0	No. of invalid 1/2 hours	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0			
	Sum of exceedances	31	Value exceeds ELV?	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y			

Signed: Robert Fairless, Environment Coordinator (via robert.fairless@lafargetarmac.com)
(authorised to sign as representative of Lafarge Tarmac Cement and Lime Ltd)

Dec-14




Daily Average	PM			Date																													
		Monthly Summary		Daily Average ELV																													
		Monthly Maximum	4.96	Daily Average																													
		No. of invalid days	0	Value Valid? (if more than 5 dropped then N else Y)	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	
		Total invalid 1/2 hours	1	No. of invalid 1/2 hours	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0
		Sum of exceedances	0	Value exceeds ELV?	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N

Signed: Robert Fairless, Environment Coordinator (via robert.fairless@lafargetarmac.com)
(authorised to sign as representative of Lafarge Tarmac Cement andf Lime Ltd)

Permit Reference Number: BL3986
Installation: Aberthaw Works
Reporting of Continuously Monitored Emissions to Air from Emission Point A1 for Volatile Organic Matter for:

Operator: Lafarge Tarmac Cement & Lime Ltd
Form Number: Air 3 / 31 August 2010
Dec-14




VOC			Date	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Daily Average	Monthly Summary		Daily Average ELV	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50	50
	Monthly Maximum	29.40	Daily Average	25.7	25.8	26.8	26	25.9	25	24	26.354	28.2	27.3	29.2	29.4	28.1	27.9	27.2	28.6	26.6	27	22.8	21			22.6	24.4	24.2	24.6	24.5	24.65	24.1835	23.3864	29.1669
	No. of invalid days	0	Value Valid? (if more than 5 dropped then N else Y)	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	Y	
	Total invalid 1/2 hours	1	No. of invalid 1/2 hours	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0
	Sum of exceedances	0	Value exceeds ELV?	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N	N

Signed: Robert Fairless, Environment Coordinator (via robert.fairless@lafargetarmac.com)
(authorised to sign as representative of Lafarge Tarmac Cement andf Lime Ltd)


Dec-14

Permit Reference Number: BL3986
Installation: Aberthaw Works
Reporting of Continuously Monitored Emissions to Air from Emission Point A1 for HCl for: Dec-14

Operator: Lafarge Tarmac Cement & Lime Ltd
Form Number: Air 4 / 31 August 2010



Signed: Robert Fairless, Environment Coordinator (via robert.fairless@lafargetarmac.com)
(authorised to sign as representative of Lafarge Tarmac Cement andf Lime Ltd)



CO		Date	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
Daily Average	Monthly Summary		Daily Average ELV																														
	Monthly Maximum	896.26	Daily Average																														
	No. of invalid days	0	Value Valid? (if more than 5 dropped then N else Y)																														
	Total invalid 1/2 hours	1	No. of invalid 1/2 hours																														
	Sum of exceedances	0	Value exceeds ELV?																														

Permit Reference Number: BL3986


Installation: Aberthaw Works

Reporting of Continuously Monitored Emissions to Air from Emission Point A1 for Sulphur Dioxide for:

Operator: Lafarge Tarmac Cement & Lime Ltd

Form Number: Air 6 / 31 August 2010


Dec-14



Signed: Robert Fairless, Environment Coordinator (via robert.fairless@lafargetarmac.com)

(authorised to sign as representative of Lafarge Tarmac Cement andf Lime Ltd)

Dec-14



Signed: Robert Fairless, Environment Coordinator (via robert.fairless@lafargetarmac.com)
(authorised to sign as representative of Lafarge Tarmac Cement and Lime Ltd)

41974