



Schedule 1

Notification of Unauthorised Release

Operator: Tata Steel UK Ltd

Authorisation: BS3905 **Location:** Llanwern Works
Newport
South Wales
NP19 4QZ

Date Submitted: 02nd April 2015

PART B
Further details of the release and results of any investigations carried out This Part B is a follow-up to the Part A Notification that was submitted on the 26/01/15, for a breach of the daily flowrate limit for effluent. As per this Notification, the breach of volumetric flowrate is considered as being directly as a result of rainfall during the period – the three months in question receiving consecutively high levels of rainfall (123, 156, and 110 mm respectively), thereby contributing to the high quarterly effluent discharge volume observed
Measures taken or intended to be taken to prevent a recurrence of the incident No additional measures are proposed currently
Measures taken, or intended to be taken, to: rectify, limit or prevent any pollution of the environment or harm which has been caused by the emission None Proposed
The dates of any PART A notifications within the previous 24 months Breach of HCl to Atmosphere consent limit at Pickle Line No 2 - 13/11/13 - 01/07/14 (This Notification) Cold Mill '5 stand' Fire - 27/09/13 Monitoring Data not reported (Lab equipment failure) - 15/11/13 - 23/02/14 Breach of Suspended Solids in Effluent - 25/12/13



Failure of Continuous pH Monitor

- 11/09/13

Failure of Oil on Water Continuous Monitor

- 25/03/14

Breach of Effluent Volume limit

- 26/01/15 (This Notification)

Name: Stephen Thomas **Position:** Lead Environmental Engineer

Signature:

A handwritten signature in blue ink, appearing to be 'ST' followed by a stylized flourish.

[Signed on behalf of Tata Steel Strip Products UK]