

Permit Reference Number: UP3831ES

Installation: TS Resins, Alyn Works

Reporting of Waste Disposal and Recovery for the year.....2018.....

| Waste Disposal and Recovery |       |               |                 |
|-----------------------------|-------|---------------|-----------------|
| Description                 | Route | Disposal      | Recovery        |
|                             |       |               |                 |
| Hazardous Waste             | D1    | 0             | -               |
|                             | D8    | 103.18        | -               |
|                             | D13   | 0             | -               |
|                             | R3    | -             | 5.275           |
|                             | R4    | -             | 0               |
|                             | Site  | -             | 0               |
| <b>Total</b>                |       | <b>103.18</b> | <b>5.275</b>    |
| Non Hazardous Waste         | D1    | 15            | -               |
|                             | D8    | 0             | -               |
|                             | D13   | 0             | -               |
|                             | R3    | -             | 1203.99         |
|                             | R4    | -             | 45              |
|                             | R10   | -             | 0               |
|                             | Site  | -             | 1656.861        |
| <b>Total</b>                |       | <b>15</b>     | <b>2905.851</b> |
| <b>TOTAL WASTE</b>          |       | <b>118.18</b> | <b>2911.126</b> |

Operator:

TS Resins Ltd

Form Number:

R1

| Trends in Waste Disposal and Recovery |             |             |                       |
|---------------------------------------|-------------|-------------|-----------------------|
| Year                                  | Parameter   |             |                       |
|                                       | Named waste | Total Waste | Waste per unit output |
|                                       |             |             |                       |
|                                       |             |             |                       |
| <b>2018</b>                           |             | 3029.306    | 0.132                 |
| <b>2017</b>                           |             | 1957.96     | 0.081                 |
| <b>2016</b>                           |             | 1409.22     | 0.063                 |
| <b>2015</b>                           |             | 1957.38     | 0.092                 |
| <b>2014</b>                           |             | 2270.977    | 0.104                 |
| <b>2013</b>                           |             | 2983.863    | 0.078                 |
| <b>2012</b>                           |             | 2817.205    | 0.070                 |
| <b>2011</b>                           |             | 2387.363    | 0.040                 |
| <b>2010</b>                           |             | 3030.798    | 0.046                 |
| <b>2009</b>                           |             | 3205.57     | 0.052                 |
| <b>2008</b>                           |             | 4231.75     | 0.071                 |
| <b>2007</b>                           |             | 5227.77     | 0.064                 |
| <b>2006</b>                           |             | 5654.91     | 0.076                 |
| <b>2005</b>                           |             | 4985.15     | 0.075                 |

Operator comments: Hazardous waste recycled on site = 0.0%    Waste recycled on site = 54.69%    Waste recycled or recovered = 96.10%

Signed .....  .....

Date: .....14/01/2019.....

(authorised to sign as representative of the Operator)