

FORM R1: WASTE RETURNS

ANNUAL SUMMARY TO 31 DECEMBER 2021

Operator: Real Alloy UK Limited

Permit Number: EP3935UC

Location: Waunarlwydd Works, Waunarlwydd, Swansea. SA5 4SF

This Report refers to the period, January 2021 - December 2021 and contains detailed and commercially sensitive information which, if this information was made publicly available, could negatively impact any competitive advantage over our competitors.

FORM R1: WASTE RETURNS

ANNUAL RETURN TO 31 DECEMBER 2021

Operator: Real Alloy, UK Limited (Swansea)

Permit Number: EP3935UC

Location: Waunarlwydd Works, Waunarlwydd, Swansea. SA5 4SF

Substance	Quantity ('000kg)	Waste Type (E.G. Hazardous)	Fate
Salt Slag	29,664	Hazardous	R4
Main baghouse filter dust	0	Hazardous	R4
Main baghouse filter dust	1290	Non-Hazardous	D9
Mudroom baghouse filter dust	0	Hazardous	R4
Refractory Waste	<0.500 ¹	Hazardous	R4
Interceptor Residue	<0.500 ²	Hazardous	R4
Oily Waste	0.500	Hazardous	R13
Main baghouse filters	<0.100 ³	Hazardous	D10
Mudroom baghouse filters	<0.100 ³	Hazardous	D10
General Non-hazardous Waste	45.96*	Non-Hazardous	R3 / R4
Canteen waste	35.22	Non-Hazardous	D1
Vehicle wash waters	77.5	Hazardous	D9

Note: If some information supplied is considered to be commercially confidential, a statement of which information this applies to and the reasons why must be specified.

Signed on behalf of Real Alloy UK Limited

Name:
Helen Williams

Signature: *Helen Williams*

Dated: 28.1.2022

¹ = Refractory Waste contains drosses/aluminium so is mixed with our saltcake and recycled.

² = Interceptor Residues contain drosses/aluminium so is mixed with our saltcake and recycled.

³ = Baghouse Filters contain baghouse dust so are put into the furnace and incinerated

*General Waste = Scrap Wood = 22.48t

Scrap Metal = 23.48

