

creu lle gwell
creating a better place



Asiantaeth yr
Amgylchedd Cymru
Environment
Agency Wales

Mr. Gareth. Price
Ashwood Farm
Grosmont
NP7 8HL

Ein Cyf:/Our ref: RP3433UF

Eich Cyf:/Your ref:

Dyddiad/Date: 21 February 2012

Dear Mr. Price,

Title: The Environmental Permitting Regulations 2010 RP3433UF Compliance Assessment Report

Thank you for your cooperation during my inspection of Ashwood Farm poultry unit on February 17th 2012 and the progress that has been made in achieving compliance with the outstanding issues from the previous inspection.

Condition 2.5.1. The housing review is now complete

Installation of new drainage tank : This has been completed and the drainage review amended accordingly

Repairs of concrete : New concrete has been laid to the front of the poultry houses

Four year reviews: The reviews for Energy , Raw Materials, Waste and Water use were all submitted during the inspection.

During the inspection the following issues were observed and need early attention :

Site Emergency Contact Detail Sign: this had been completed on the day of the inspection but was not on display at the site entrance, it needs to be put up as soon as possible.



Fuel Storage Tank: The single skinned metal tank seen during the inspection was not bunded and as such not compliant with the SSAFO Wales 2010 regulations . Either a bund needs to be constructed which can contain 110% of the capacity of the tank and encloses the tank fittings or the tank needs to be replaced with an integrally bunded tank. This should be completed within 3 months of the date of the inspection

Yours sincerely



CHRISTOPHER GARDENER

Swyddog yr Amgylchedd/Environment Officer

Llinell uniongyrchol/Direct dial 02920 582763

Ffâcs uniongyrchol/Direct fax 01600 772202

E-bost uniongyrchol/Direct e-mail Chris.Gardener@environment-agency.gov.uk