Permit Reference Number: BV7559IE
Installation: Llangefni

Operator: 2 Sisters Poultry Ltd
Form Number: R1

Reporting of Waste Disposal and Recovery for the year 2018

Waste Description	Disposal		Recovery
	Route	Tonnes	Tonnes
1) Hazardous Waste			
Total Hazardous Waste		0	0
Oils		0	4.68
Fluorescent Tubes		0	0
2) Non Hazardous Waste			
Total Non Hazardous Waste		0	9794.98
General Waste	Landfill	0	0
TOTAL WASTE			9799.66

Trends in Waste Disposal and Recovery			
Year	Parameter		
	Named Waste	Total Waste	Waste per tonne product
2016		26571	
2017		10327	0.184
2018		9799	0.2108

Operator's Comments:

Signed ..... Date ...26.02.19.....
(authorised to sign as representative of the Operator)