

Figure 10.1 Location of boreholes 1 to 4 in a field to the north east of the quarry




Figure 10.2 Extent of visible evidence of instability