

**Sea View Farm 2 Landfill Site**  
**Monthly Gas Monitoring**  
**December 2015**

**TerraConsult**

Date	Monitored By	Monitoring Point	Atmospheric Pressure mbar	Atmospheric Pressure Comment	Relative Pressure mbar	Flow l/h	CH <sub>4</sub> % v/v	CO <sub>2</sub> % v/v	O <sub>2</sub> % v/v	CO ppm	H <sub>2</sub> S ppm	Gas Analyser	Conditions @ Monitoring
07/12/2015	J. Parker	G2	Replacement bung required									GFM436	Partly overcast, 11 ° c
		G3	1004	Falling	<0.01	<0.01	<0.1	4.7	11.4	<1	<1		
		G4	1004	Falling	<0.01	<0.01	<0.1	4.2	14	<1	<1		
		G5	1004	Falling	<0.01	<0.01	<0.1	0.9	18.8	<1	<1		
		G6	1004	Falling	<0.01	<0.01	<0.1	4.8	5.5	<1	<1		
		GV1	1004	Falling	<0.01	<0.01	<0.1	<0.1	20	<1	<1		
		GV2	1005	Falling	<0.01	<0.01	<0.1	<0.1	20.1	<1	<1		
		LC	1005	Falling	<0.01	<0.01	<0.1	<0.1	20.2	<1	<1		
		502	Replacement bung required - Replaced 20/01/2016										
		503	1005	Falling	0.86	11.5	4	7.8	0.6	<1	<1		
		504	Removed										
		505	1005	Falling	<0.01	<0.01	<0.1	<0.1	20	<1	<1		
		506	Replacement bung required - Replaced 20/01/2016										

**NOTES**

Data value in brackets indicates peak reading

NGV - No Gas Valve