

Schedule 1 • Notification of abnormal emissions

Part A

| | | | |
|--|-------|---|---|
| Permit Number | | EPR/WP3836ZF | |
| Name of Operator | | Tradebe Healthcare National Ltd | |
| Location of Installation | | Wrexham Clinical Waste Incinerator, Marlborough Road, Wrexham Industrial Estate, Wrexham LL13 9RJ | |
| Location of the emission | | A1 Emission point | |
| Time and date of the emission | | 07 April 2022 02h29 and 21h29 | |
| Substance(s) emitted | Media | Best estimate of the quantity or the rate of emission | Time during which the emission took place |
| SO2 | Air | 302.5 297.1 | 02h29 21h29 |
| Measures taken, or intended to be taken, to stop the emission: | | Loading of waste immediately ceased on both occasions until emissions back under control. | |

| | |
|-----------|---------------|
| Name* | Peter Stunden |
| Post | Site Manager |
| Signature | |
| Date | 08 April 2022 |

• authorised to sign on behalf of Tradebe Healthcare National Limited

PART B

| | | |
|---|--|--|
| Any more accurate information on the matters for notification under Part A. | Both emissions were short in duration and the plant was able to restart loading within short period of time. | |
| Measures taken, or intended to be taken, to prevent a recurrence of the incident | Due to the nature of the product, unless weight, or specific product show up it is difficult to determine what is being processed. | |
| Measures taken, or intended to be taken, to rectify, limit or prevent any pollution of the environment or harm which has been or may be caused by the emission | Teams are trained to stop loading immediately and only recommence processing once emission are back within parameters. | |
| The dates of any unauthorised emissions from the Installation in the preceding 24 months. | | |
| Name* | Peter Stunden | |
| Post | Site Manager | |
| Signature | | |
| Date | 08 April 2022 | |