

Addendum to Egniol Report 3240/STA/PF dated 8 September 2008

Nant Ffordd Landfill Site

This report relates to a stability assessment of Nant Fforch landfill site. There are a number of plans and cross sectional drawings within this report.

It should be noted that this report has the north reference incorrectly shown on plans 3240.NF.01 and 3240.NF.02. The plan annotation to north is in fact pointing eastward.

The plans and text of the report should be read with this revision in mind.

The stability assessment is not affected by this error.

Note made by Clare Walters of Ceri Environmental Consulting Ltd on 8th January 2016.